



ALL CLASSES FROM 7:30 AM TO 4 PM except as noted

ALTERNATE TIMES AND/OR LOCATION "LATE CLASS ARRIVALS ARE NOT PERMITTED"

Asbestos Worker class requires hard hat, rubber boots and swim trunks/attire for Decon

March 2025	Class Name	Hours	*Alt Time/Location
3-7	Construction Math	40	7:30 AM-4:00 PM/Portland
3-7	Concrete 2	40	7:30 AM-4:00 PM/Portland
10-14	General Construction 1	40	7:30 AM-4:00 PM/Portland
10-14	Assessment	40	7:30 AM-4:00 PM/Portland
10-14	Rigging & Signaling	40	7:30 AM-4:00 PM/Portland
10-11	OSHA 10	12	7:30 AM-4:00 PM/Portland
13-14	Forklift Initial	16	7:30 AM-4:00 PM/Portland
14	Washington Asbestos Supervisor Refresher	8	7:30 AM-4:00 PM/Portland
17-21	Concrete	40	7:30 AM-4:00 PM/Portland
17-21	OSHA 30	40	7:30 AM-4:00 PM/Portland
17-21	Grade Checking	40	7:30 AM-4:00 PM/Portland
17-21	Blueprint Reading	40	7:30 AM-4:00 PM/Portland
17-21	Oregon Asbestos Worker Initial	40	7:30 AM-4:00 PM/Portland
24-28	General Construction 1	40	7:30 AM-4:00 PM/Portland
24-28	Rigging & Signaling	40	7:30 AM-4:00 PM/Portland
24-28	Assessment	40	7:30 AM-4:00 PM/Portland
24	Flagger	8	7:30 AM-4:00 PM/Portland
24	Washington Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
25	Oregon Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
25	First Aid/CPR	8	7:30 AM-4:00 PM/Portland
26-28	ICRA	24	7:30 AM-4:00 PM/Portland
28	Forklift Refresher	8	7:30 AM-4:00 PM/Portland
29 (Saturday)	Oregon Asbestos Supervisor Refresher	8	7:30 AM-4:00 PM/Portland

Apprentice attendance is **Mandatory**.

JOURNEYMAN **PLEASE** call **Local 737** at 541-801-2209 (required for class registration)

Lodging available if you live more than 60 miles or more from campus, please request at registration.

Failure to confirm your attendance will cancel your lodging reservation.

48 HR notice for class **CANCELLATION** required please.

*If the training you need is NOT listed, please **call the Training Center** at 541-745-5513.

Certification	Expires
Aerial & Scissor Lift	3 years after issue date
Flagger	3 years after issue date
First Aid	2 years after issue date
Forklift	3 years after issue date
Rigging & Signaling	3 years after issue date
TCS	3 years after issue date
Asbestos	1 year after issue date
CPR/First Aid/AED	2 years after issue date
OSHA Cards	Refresher every 4 years



ALL CLASSES FROM 7:30 AM TO 4 PM except as noted

ALTERNATE TIMES AND/OR LOCATION "LATE CLASS ARRIVALS ARE NOT PERMITTED"

Asbestos Worker class requires hard hat, rubber boots and swim trunks/attire for Decon

April 2025	Class Name	Hours	*Alt Time/Location
7-11	Assessment	40	7:30 AM-4:00 PM/Portland
7-11	OSHA 30	40	7:30 AM-4:00 PM/Portland
7-11	Scaffold Builder	40	7:30 AM-4:00 PM/Portland
7	Washington Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
8	Oregon Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
9	Oregon Asbestos Supervisor Refresher	8	7:30 AM-4:00 PM/Portland
10-11	OSHA 10	12	7:30 AM-4:00 PM/Portland
11	First Aid/CPR	8	7:30 AM-4:00 PM/Portland
14-18	Blueprint Reading	40	7:30 AM-4:00 PM/Portland
14-18	Pipelaying	40	7:30 AM-4:00 PM/Portland
14-18	Oregon Asbestos Worker Initial	40	7:30 AM-4:00 PM/Portland
14	Flagger	8	7:30 AM-4:00 PM/Portland
15-16	Forklift Initial	16	7:30 AM-4:00 PM/Portland
17-18	Aerial & Scissor Lift	16	7:30 AM-4:00 PM/Portland
21-25	Assessment	40	7:30 AM-4:00 PM/Portland
21-25	Mason Tending	40	7:30 AM-4:00 PM/Portland
21-25	Construction Math	40	7:30 AM-4:00 PM/Portland
21-25	Oregon Asbestos Supervisor Initial	40	7:30 AM-4:00 PM/Portland
25	Forklift Refresher	8	7:30 AM-4:00 PM/Portland
28- May 2	General Construction 1 (Apprentices Only)	40	7:30 AM-4:00 PM/Portland
28- May 2	Concrete	40	7:30 AM-4:00 PM/Portland
28- May 2	General Construction 2 (Apprentices Only)	40	7:30 AM-4:00 PM/Portland
28- May 2	Oregon Asbestos Worker Initial	40	7:30 AM-4:00 PM/Portland

May 2025	Class Name	Hours	*Alt Time/Location
5-9	General Construction 2 (Apprentices Only)	40	7:30 AM-4:00 PM/Portland
5-9	Assessment	40	7:30 AM-4:00 PM/Portland
5-9	Concrete Cutting & Coring	40	7:30 AM-4:00 PM/Portland
5	Washington Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
6	Oregon Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
7-9	ICRA	24	7:30 AM-11:30 AM/Portland
12-16	Concrete	40	7:30 AM-4:00 PM/Portland
12-16	Rigging & Signaling	40	7:30 AM-4:00 PM/Portland
12-16	Assessment	40	7:30 AM-4:00 PM/Portland
12-16	Oregon Asbestos Worker Initial	40	7:30 AM-4:00 PM/Portland
12	Flagger	8	7:30 AM-4:00 PM/Portland
13-14	OSHA 10	12	7:30 AM-4:00 PM/Portland
15	First Aid/CPR	8	7:30 AM-4:00 PM/Portland
19-23	Demo	40	7:30 AM-4:00 PM/Portland
19-23	General Construction 2 (Apprentices Only)	40	7:30 AM-4:00 PM/Portland
19-23	General Construction 3 (Apprentices Only)	40	7:30 AM-4:00 PM/Portland
19-23	Construction Math	40	7:30 AM-4:00 PM/Portland

Apprentice attendance is **Mandatory**.

JOURNEYMAN **PLEASE** call **Local 737** at 541-801-2209 (required for class registration)

Lodging available if you live more than 60 miles or more from campus, please request at registration.

Failure to confirm your attendance will cancel your lodging reservation.

48 HR notice for class **CANCELLATION** required please.

REQUIRED - Appropriate footwear and work clothes are Mandatory

*If the training you need is NOT listed, please call the Training Center at 541-745-5513.

ALL CLASSES FROM 7:30 AM TO 4 PM except as noted

ALTERNATE TIMES AND/OR LOCATION "LATE CLASS ARRIVALS ARE NOT PERMITTED"

Asbestos Worker class requires hard hat, rubber boots and swim trunks/attire for Decon

June 2025	Class Name	Hours	*Alt Time/Location
9-13	General Construction 2 (Apprentices Only)	40	7:30 AM-4:00 PM/Portland
9-13	Oregon Asbestos Worker Initial	40	7:30 AM-4:00 PM/Portland
9-13	Rigging & Signaling	40	7:30 AM-4:00 PM/Portland
9-13	Assessment	40	7:30 AM-4:00 PM/Portland
9-13	Concrete	40	7:30 AM-4:00 PM/Portland
16	Washington Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
16-17	OSHA 10	12	7:30 AM-4:00 PM/Portland
16-17	Aerial & Scissor Lift	16	7:30 AM-4:00 PM/Portland
16-17	Forklift Initial	16	7:30 AM-4:00 PM/Portland
16-18	ICRA	24	7:30 AM-4:00 PM/Portland
17	Oregon Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
18	Oregon Asbestos Supervisor Refresher	8	7:30 AM-4:00 PM/Portland
18	First Aid/CPR	8	7:30 AM-4:00 PM/Portland
18	Forklift Refresher	8	7:30 AM-4:00 PM/Portland
23-27	General Construction 2 (Apprentices Only)	40	7:30 AM-4:00 PM/Portland
23-27	Grade Checking	40	7:30 AM-4:00 PM/Portland
23-27	Scaffold Builder	40	7:30 AM-4:00 PM/Portland
23-27	Blueprint Reading	40	7:30 AM-4:00 PM/Portland
30	Flagger	8	7:30 AM-4:00 PM/Portland
30	Oregon Asbestos Worker Refresher	8	7:30 AM-4:00 PM/Portland
30 - July 1	OSHA 10	12	7:30 AM-4:00 PM/Portland
30 - July 1	Forklift Initial	16	7:30 AM-4:00 PM/Portland
July 1	First Aid/CPR	8	7:30 AM-4:00 PM/Portland
July 2	Oregon Asbestos Supervisor Refresher	8	7:30 AM-4:00 PM/Portland
July 2	Forklift Refresher	8	7:30 AM-4:00 PM/Portland
July 2	Scaffold User	8	7:30 AM-4:00 PM/Portland

Apprentice attendance is **Mandatory**.

JOURNEYMAN **PLEASE** call Local 737 at 541-801-2209 (required for class registration)

Lodging available if you live more than 60 miles or more from campus, please request at registration.

Failure to confirm your attendance will cancel your lodging reservation.

48 HR notice for class **CANCELLATION** required please.

*If the training you need is NOT listed, please call the Training Center at 541-745-5513.

Certification	Expires
Aerial & Scissor Lift	3 years after issue date
Flagger	3 years after issue date
First Aid	2 years after issue date
Forklift	3 years after issue date
Rigging & Signalling	3 years after issue date
TCS	3 years after issue date
Asbestos	1 year after issue date
CPR/First Aid/AED	2 years after issue date
OSHA Cards	Refresher every 4 years